

!! URGENT!!

Date: 21 December 2022

Subject: Colombia

Enroute Airways Cycle 2213

Enroute Airway data incorrect

Jeppesen NavData for cycle 2213, effective 29 DEC 2022 contains incorrect information for portions of 2 airways within Colombia. Airway UP525 and airway UQ124 includes incorrect coordinates for PALUG waypoint and VULNO waypoint respectively and as a result the airway bearings and mileages are incorrect.

The correct information, including correct coordinates for the waypoints is provided in the tables below.

Airway UP525

Start Fix	End Fix	Bearings	Mileage	MEA
Barrancabermeja (EJA) VOR	PALUG waypoint (N04 01.8 W073 01.7)	173°/353°	185 NM	FL250
PALUG waypoint	San Jose Del Guaviare (SJE) VOR	174°/354°	92 NM	FL250

Airway UQ124

_ · · · · · · · · · · · · · · · · · · ·						
Start Fix	End Fix	Bearings	Mileage	MEA		
UGOSA waypoint	VULNO waypoint (N08 19.3 W073 20.6)	179°/359°	86 NM	FL250		
VULNO waypoint	Piedecuesta (PIE) VOR	179°/359°	87 NM	FL250		

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2301, effective 26 January 2023. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: Notices and Alerts.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

+1-303-328-4445 (Western Hemisphere)

+49 610 250 8175 (Eastern Hemisphere)

E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.