

NavData[®] Alert

!! URGENT !!

Date: 14 November 2022

Subject: Ouagadougou, Burkina Faso (DFFD) Multiple procedures Cycle 2211

Procedure coding outdated

Jeppesen NavData for cycle 2211, effective 03 November 2022, contains incorrect data for Ouagadougou, Burkina Faso (DFFD). ASECNA AMDT 011-22 effective, 03 NOV 22 was received after the ICAO specified date for aeronautical information publication.

RNAV STAR TUMUT 1P (TUMU1P) should read **TUMUT 2P (TUMU2P)** - speed restriction **MAX 230kts** is missing at waypoint **POTIM**.

RNAV SIDS ANIXA 1N (ANIX1N), EDGIB 1N (EDGI1N), NAVON 1N (NAVO1N), NUSUR 1N (NUSU1N), OXIDU1N (OXID1N), TUMUT 1N (TUMU1N), TUXID 1N (TUXI1N), UMOVO 1N (UMOV1N) - speed restriction at waypoints FD702 and FD707 should read MAX 250kts.

RNAV STARs TUXID 1P (TUXI1P) and ANIXA 1P (ANIX1P) - speed restriction MAX 230kts is missing at waypoint POTIM.

RNAV STARS ARIBO 1A (ARIB1A), BIKOR 1A (BIKO1A), EDGAS 1B (EDGA1B), INEGO 1B (INEG1B), LIKEM 1P (LIKE1P), NUTET 1P (NUTE1P), OPENA 1P (OPEN1P), POROK 1P (PORO1P), SEMOS 1P (SEMO1P), TIXOT 1P (TIXO1P) should not be used.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at: +1-303-328-4445 (Western Hemisphere) +49 610 250 8175 (Eastern Hemisphere) E-mail: <u>navdatasupport@boeing.com</u>

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2212, effective 01 December 2022. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: <u>Notices and Alerts</u>.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at: +1-303-328-4445 (Western Hemisphere) +49 610 250 8175 (Eastern Hemisphere) E-mail: <u>navdatasupport@boeing.com</u>

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.