

Special Notice

URGENT

Date: 27 September 2022

Subject: Incorrect heading on Standard Terminal Arrival

Cycle 2209 & 2210

The following procedure was delivered with an incorrect heading.

| Airport | Procedure | Error |
|---------|------------|------------------------|
| KPIT | DEMME FOUR | The runway transitions |
| | (DEMME4) | RWY 28L/28C/28R |
| | | should terminate on a |
| | | heading of 71°. |

AeroNavData advises to use the procedure with extreme caution until an updated data delivery is made. The data will be updated to reflect the latest source in the cycle 2211 data effective Thursday, Nov 03, 2022.

Special notices are disseminated to notify customers of issues with navigational data which may affect flight operations or safety. Information contained herein should be immediately relayed to appropriate personnel!

Important: Check NOTAMs and other pertinent information prior to flight.

All questions regarding this Special Notice should be addressed to: Email: production@aeronavdata.com

Fax: (314) 729-7006

9735 Landmark Pkwy, Suite 200 St. Louis, MO 63127