



AERONAVDATA™

Special Notice

URGENT

Date: 27 December 2022
Subject: Colombia Enroute Airways
Cycle 2213

For cycle 2213, effective 29 December 2022 Airway UP525 and UQ124 in Colombia was published with incorrect coordinates for PALUG and VULNO waypoints. As a result, the airway bearings and distances are incorrect.

Airway	Segment	Error
UP525	EJA VOR to PALUG	The bearings and distance should be 173°/353° and 185 NM. The correct coordinates for PALUG should be: N04 01 46 W073 01 39
UP525	PALUG to SJE VOR	The bearings and distance should be 174°/354° and 92 NM.
UQ124	UGOSA to VULNO	The bearings and distance should be 179°/359° and 86 NM. The correct coordinates for VULNO should be: N08 19 19 W073 20 38
UQ124	VULNO to PIE VOR	The bearings and distance should be 179°/359° and 87 NM.

AeroNavData advises to use the airways with extreme caution until an updated data delivery is made. The data will be updated to reflect the latest source in the cycle 2301 data effective Thursday, January 26, 2023.

Special notices are disseminated to notify customers of issues with navigational data which may affect flight operations or safety. Information contained herein should be immediately relayed to appropriate personnel!

Important: Check NOTAMs and other pertinent information prior to flight.

All questions regarding this Special Notice should be addressed to:

Email: production@aeronavdata.com

Fax: (314) 729-7006

9735 Landmark Pkwy, Suite 200
St. Louis, MO 63127