

!! URGENT!!

Date: 19 August 2022

Subject: Tokyo, Japan

(Haneda) Tokyo Intl (RJTT) ILS or LOC Rwy 16L

Cycle 2208

Stepdown fix incorrect

Jeppesen NavData for cycle 2208, effective 11 August 2022, contains incorrect data for (Haneda) Tokyo Intl; Tokyo, Japan (RJTT).

ILS or LOC Rwy 16L – step down fix 38LOC should read: 31LOC, 1010'. Coordinates should read: N 35° 36'18.09" E 139° 45' 31.50".

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2209, effective 8 September 2022. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: Notices and Alerts. Please refer to the Tokyo, Japan (RJTT) 11-18 chart dated 6 MAR 20 for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

+1-303-328-4445 (Western Hemisphere) +49 610 250 8175 (Eastern Hemisphere)

E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.