

!! URGENT !!

Date: 06 September 2022

Subject: Toronto, Canada Lester B Pearson Intl (CYYZ) Cycle 2209

TWYs name and status incorrect.

Jeppesen Airport Moving Map and A816 formatted data for cycle 2209, effective 08 September 2022, contain incorrect data for Lester B Pearson Intl, Toronto, Canada (CYYZ). According to AIP Canada SUP 62/22, effective 08 September 2022, published 30 August 2022, "A reconfiguration of the published depiction of "Holding Bay RWY 06L," "Taxiway Delta & Delta 6" adjacent to the threshold of Runway 06L and Runway 06R at Toronto/Lester B. Pearson International Airport" has been postponed to 03 November 2022. As a result following changes were not included in cycle 2209 data:

- TWY D6 (North of THR RWY 06L) is closed
- TWY D8 (North of THR RWY 06L) shall read TWY D
- TWY D8 (South of THR RWY 06L) shall read TWY D6
- TWY D10 (South of THR RWY 06L) shall read TWY D

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2210, effective 06 October 2022. Until then this Alert will be posted on the Jeppesen Web site: <u>Notices and Alerts</u>. Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support

at: U.S. Toll Free: 1-800-537-7725 Direct: 1-303-328-4170 E-mail: gisdatasupport@boeing.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.