



JEPPESEN[®]
Airport Moving Map Alert

!! URGENT !!

Date: 08 September 2202

**Subject: Munich, Germany
Munich (EDDM)
Cycle 2209**

TWY E3 on Apron 3 status incorrect.

Jeppesen Airport Moving Map and A816 formatted data for cycle 2209 (effective 08 September 2022) contain incorrect data for Munich; Munich, Germany (EDDM). German AIP SUP 16/22, effective 16 June 2022, published 09 June 2022 introduced “Overhaul of taxiway E3 on apron 3 of Munich Airport”. Phase 2 is not reflected in cycle 2209 data as do not cover entire AIRAC cycle.

Following changes are valid from 22 August 2022 until 30 September 2022 (Phase 2 duration):

- TWY E3 (between Stand 311 and Stand 321) is closed

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2210, effective 06 October 2022. Until then this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support
at:

U.S. Toll Free: 1-800-537-7725

Direct: 1-303-328-4170

E-mail: gisdatasupport@boeing.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.

EDDM_2209