

Navigation Database Addendum

AIRAC 2212 – Issue 12

NOTAM A0374/22 effective 25th November 2022

VRMV Maamigili Island Villa Intl Maamigili

RWY 09

RWY 09 landing threshold temporarily displaced by 300m until 25-FEB-2023 EST.

APCHs in NavDB do not lead to the displaced landing threshold, vertical guidance should not be used.

Navdata will be updated effective AIRAC cycle 2213.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Friday, 25th November 2022

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com

Navigation Database Addendum

AIRAC 2211 – Issue 13

NOTAM A0374/22 effective 25th November 2022

VRMV Maamigili Island Villa Intl Maamigili

RWY 09

RWY 09 landing threshold temporarily displaced by 300m until 25-FEB-2023 EST.
APCHs in NavDB do not lead to the displaced landing threshold, vertical guidance should not be used.

Navdata will be updated effective AIRAC cycle 2213.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Friday, 25th November 2022

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com