

Navigation Database Addendum

AIRAC 2213 – Issue 2

VO AIP SUP 189 effective 8th December 2022

VOPB Port Blair

APCH LOC RWY 04

LOC 04 APCH should not be used.

LOC 04-Y and LOC 04-Z APCHs are missing.

Navdata will be updated effective AIRAC cycle 2301.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Thursday, 15th December 2022

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com



Lufthansa Systems

Navigation Database Addendum

AIRAC 2212 – Issue 16

VO AIP SUP 189 effective 8th December 2022

VOPB Port Blair

APCH LOC RWY 04

LOC 04 APCH should not be used.

LOC 04-Y and LOC 04-Z APCHs are missing.

Navdata will be updated effective AIRAC cycle 2301.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Thursday, 15th December 2022

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com