

Navigation Database Addendum

AIRAC 2301 – Correction to Issue 6
AIRAC AMDT HE 1/23 effective 26th January 2023

HECC Cairo FIR

AWY L677, V603, W727

- AWY L677: WPT KUPTI missing.
Routing should read: ...SHM - **KUPTI** - KAPIT...
- AWY V603: WPT ALSOB missing.
Routing should read: ...SISIK - **ALSOB** - DASOT...
- AWY W727: WPT DEDEV missing.
Routing should read: ...**OBTAV** - **DEDEV** – SHM...

Navdata will be updated effective AIRAC cycle 2302.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Thursday, 12th January 2023

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com