



AN AIRBUS COMPANY

## ERROR NOTIFICATION BULLETIN

**NAVBLUE Reference:** 2211-03E

**Notification Published date:** 03-11-2022

**Product Affected:** Navigation+

**AIRAC Cycle:** 2211

**Effective Date:** 03-11-2022

**Country:** Botswana

**Subject:** MAUN-INTL (FBMN) Runway Bearings

**Source:** AIP 220714

**Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2211**

### MAUN-INTL (FBMN)

The magnetic and true bearings for the runways at FBMN are erroneously published in state information. As a result, the following errors occurred in cycle 2211.

RWY 08/26 - Magnetic bearing coded as 85/265 respectively but should be 76/256.

RWY 08/26 - True bearing coded as 76/256 respectively but should be 67/247.

**These changes will be incorporated in NAVBLUE databases for cycle 2212**