

**!! URGENT !!**

**Date:** 26 July 2022

**Subject:** Sihanouk, Cambodia  
Sihanouk Intl (VDSV)  
Multiple procedures  
Cycle 2207

*Procedure coding outdated*

Jeppesen NavData for cycle 2207, effective 14 July 2022, contains incorrect data for Sihanouk Intl; Sihanouk, Cambodia (VDSV). SUP A01-A02-A03-22 AIRAC - 14 JUL 22 was received after the ICAO specified date for aeronautical information publication.

**Below procedures should not be used:**

- VOR DME Rwy 21
- RNAV (GNSS) Rwy 21

**Below procedures are missing from library:**

- ILS Rwy 21
- RNAV Visual Rwy 03
- RNAV SID ATNAB 2A [ATNA2A]
- RNAV STAR ATNAB 2A [ATNA2A]
- RNAV SID ATNAB 2B [ATNA2B]
- RNAV STAR ATNAB 2B [ATNA2B]
- RNAV SID DOXIB 2A [DOXI2A]
- RNAV STAR DOXIB 2A [DOXI2A]
- RNAV SID DOXIB 2B [DOXI2B]
- RNAV STAR DOXIB 2B [DOXI2B]
- RNAV SID IPGIP 2A [IPGI2A]
- RNAV STAR IPGIP 2A [IPGI2A]
- RNAV SID IPGIP 2B [IPGI2B]
- RNAV STAR IPGIP 2B [IPGI2B]
- RNAV SID LIKBU 2A [LIK2A]
- RNAV SID LIKBU 2B [LIK2B]
- RNAV SID NUMDI 2A [NUMD2A]
- RNAV STAR NUMDI 2A [NUMD2A]
- RNAV SID NUMDI 2B [NUMD2B]
- RNAV STAR NUMDI 2B [NUMD2B]

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO  
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData in cycle 2208. Until then an entry will appear in the NavData Change Notices beginning and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have any questions concerning this Chart Alert, please contact Chart Support at:

**+1 (303) 328-6776 (Western Hemisphere)**

**+49 (6102) 50-8174 (Eastern Hemisphere)**

**U.S. Toll Free: 1-800-353-2107**

**E-mail: [ChartSupport@boeing.com](mailto:ChartSupport@boeing.com)**

Chart Alerts are published to advise users of significant issues in Jeppesen chart data which may affect aircraft operations. Chart Alerts are distributed to chart Users and are also available on Jeppesen's Web site at [www.jeppesen.com](http://www.jeppesen.com).