

!! URGENT!!

Date: 06 October 2022

Subject: Argentina

Cycle 2210

Obstacles missing

Jeppesen Obstacle Database for cycle 2210, effective 06 October 2022, contains incorrect data for multiple locations. The following Argentina AIP SUPs, effective 30 September 2022, 05 October 2022 and 06 October, were received after 2210 AIRAC cycle data processing due date. Therefore, entire content of the below listed sources is not reflected in the Obstacle Data.

Argentina AIP SUP	Effective Date	Associated Airport
A26/2022	30 September 2022	SADF
A33/2022	30 September 2022	SATR
A36/2022	30 September 2022	SANU
A43/2022	05 October 2022	SAMR
A44/2022	05 October 2022	SARE
A45/2022	05 October 2022	SAWE
A46/2022	05 October 2022	SANT
A47/2022	05 October 2022	SAVV
A48/2022	06 October 2022	SAAP

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised data will appear in Jeppesen Obstacle Database for cycle 2211, effective 03 November 2022. Until then this Alert will be posted on the Jeppesen Web site: <u>Notices and Alerts</u>. Please refer to the local NOTAMs for valid information.

If you have questions concerning this Obstacle Alert, please contact Jeppesen Technical Support at: U.S. Toll Free: 1-800-353-2107 | extension 4445

Direct: 1-303-328-4445 E-mail: gisdatasupport@boeing.com

Obstacle Alerts are published to advise users of significant issues in Jeppesen Obstacles Database which may affect flight operations or safety. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site. Different avionics equipment and computer systems use and display obstacle data differently. Avionics users should consult with their database update Service Provider for definitive information on whether their system is affected by this Alert.