

!! URGENT !!

Date: 09 August 2022

Subject: Orlando, Florida Orlando Intl (KMCO) Cycle 2208

TWY name incorrect

Jeppesen Airport Moving Map and A816 formatted data for cycle 2208, effective 11 August 2022, contain incorrect data for Orlando Intl; Orlando, Florida (KMCO). TWY A name (west of RWY 18R, portion parallel to TWY B2) is incorrect and shall read TWY B1.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2209, effective 08 September 2022. Until then this Alert will be posted on the Jeppesen Web site: <u>Notices and Alerts</u>. Please refer to the local NOTAMs and Orlando, Florida (KMCO) 20-9 chart dated 17 SEP 21 for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at: U.S. Toll Free: 1-800-537-7725 Direct: 1-303-328-4170 E-mail: <u>GISDataSupport@boeing.com</u>

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.