



JEPPESEN[®]

Airport Moving Map Alert

!! URGENT !!

Date: 12 October 2022

Subject: Delhi, India
Indira Gandhi Intl (VIDP)
Cycle 2210

TWY names incorrect.

Jeppesen Airport Moving Map and A816 formatted data for cycle 2210, effective 06 October 2022, contain incorrect data for Indira Gandhi Intl; Delhi, India (VIDP). India AIRAC AIP SUP 153/22, published 25 August 2022, effective 06 October 2022, introduced "Re-designation of Taxiways in phased manner at Indira Gandhi International Airport, Delhi (VIDP)". The following changes are not reflected in cycle 2210 data as do not cover entire AIRAC cycle.

Following changes are valid from 09:30 [UTC] on 13 October 2022 (Part 2):

- TWY CW1 is renamed to TWY C
- TWY CW2 (between TWY N and TWY Y) is renamed to TWY A

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2211, effective 03 November 2022. Until then this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the local NOTAMs for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support at:

U.S. Toll Free: 1-800-537-7725

Direct: 1-303-328-4170

E-mail: gisdatasupport@boeing.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.

VIDP_2210