

!! URGENT !!

Date: 29 November 2022

Subject: Sydney, Australia Kingsford Smith (YSSY) Cycle 2212

Hotspot missing

Jeppesen Airport Moving Map and A816 formatted data for cycle 2212, effective 01 December 2022 contain incorrect data for Kingsford Smith; Sydney, Australia (YSSY). Australia DAP EAST 173/22, effective 01 December 2022 introduced new Hotspot at AER RWY 34R. This change is not reflected in cycle 2112 data.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised data will appear in Jeppesen Airport Moving Map and A816 formatted data for cycle 2213, effective 29 December 2022. Until then this Alert will be posted on the Jeppesen Web site: <u>Notices and Alerts</u>. Please refer to the local NOTAMs and Kingsford Smith, Sydney, Australia (YSSY) 10-9 chart dated 25 NOV 2022, effective 01 DEC 2022 for valid information.

If you have questions concerning this Airport Moving Map Alert, please contact Jeppesen Technical Support

at: U.S. Toll Free: 1-800-537-7725 Direct: 1-303-328-4170 E-mail: gisdatasupport@boeing.com

Airport Moving Map Alerts are published to advise users of significant issues in Jeppesen Airport Moving Map and A816 data which may affect aircraft ground operations. These Alerts are distributed to affected Airport Moving Map users. Different avionics equipment and computer systems use and display Airport Moving Map and data derived from A816 differently. End Airport Moving Map and A816 data users should consult with their Service Provider for definitive information on whether their system is affected by this Alert.

