



JEPPESEN[®]
NavData[®] Alert

!! URGENT !!

Date: 05 January 2023
Subject: Yaounde, Cameroon
Nsimalen (FKYS)
Multiple procedures
Cycle 2213

Procedure coding outdated

Jeppesen NavData for cycle 2213, effective 29 December 2022, contains incorrect data for Nsimalen; Yaounde, Cameroon (FKYS). AMDT 013-22 - effective 29 DEC 22 was received after the ICAO specified date for aeronautical information publication.

- RNP Rwy 19, ILS W or LOC W Rwy 19: Waypoint BOSKI should read **TINET**
- RNAV STARs AKMUT 2B, EBSAK 2B and IKREX 2B renamed to **AKMUT 2T**, **EBSAK 2T** and **IKREX 2T**. Waypoint BOSKI should read **TINET**

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2301, effective 26 January 2023. Until then an entry will appear in the NavData Change Notices beginning and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
+1-303-328-4445 (Western Hemisphere)
+49 610 250 8175 (Eastern Hemisphere)
E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.