

Navigation Database Addendum

AIRAC 2212 – Issue 8

AIP SU effective 6th October 2022

SUMU Montevideo Carrasco Intl/Gen C L Berisso

APCH VOR Z RWY 25

- Transition ASOSA: Speed at waypoint ASOSA should read max. 230KT
- Transition VUPRI: Speed at waypoint VUPRI should read max. 230KT

Navdata will be updated effective AIRAC cycle 2213.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Tuesday, 22nd November 2022

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com

Navigation Database Addendum

AIRAC 2211 – Issue 10

AIP SU effective 6th October 2022

SUMU Montevideo Carrasco Intl/Gen C L Berisso

APCH VOR Z RWY 25

- Transition ASOSA: Speed at waypoint ASOSA should read max. 230KT
- Transition VUPRI: Speed at waypoint VUPRI should read max. 230KT

Navdata will be updated effective AIRAC cycle 2213.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Tuesday, 22nd November 2022

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com