

Navigation Database Addendum

AIRAC 2213 – Issue 14 NOTAM G0016/23 effective 9th January 2023 SUP 03/2023

VERC Ranchi Birsa Munda

APCH ILS RWY 31-Z, LOC RWY 31-Z

Due to late receipt of document following procedures are not updated in database:

ILS RWY 31-Z LOC RWY31-Z

Navdata will be updated effective AIRAC cycle 2301.

Please disseminate this information to all affected crews

Lufthansa Systems FMS Customer Support Friday, 6th January 2023

All valid FSAs/NDAs are available on <u>http://fms-info.lhsystems.com</u> For any inquiries, please contact <u>fms.support@lhsystems.com</u>