

Navigation Database Addendum

AIRAC 2301 – Issue 9

SUP LF 55/2022 effective 19th May 2022;

LF SUP Checklist effective 19th January 2023;

NOTAM LF F0103/23 effective 25th January 2023

LFEE Reims FIR

Navaid STR VOR/DME

Coordinates should read **N48-30.3 E007 34.3** (N48-30-19.40 E007-34-19.10)

Frequency **115.6 MHz**

Navdata will be updated effective AIRAC cycle 2302.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Friday, 20th January 2023

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>

For any inquiries, please contact fms.support@lhsystems.com

Navigation Database Addendum

AIRAC 2213 – Issue 17

SUP LF 55/2022 effective 19th May 2022;

LF SUP Checklist effective 19th January 2023;

NOTAM LF F0103/23 effective 25th January 2023

LFEE Reims FIR

Navaid STR VOR/DME

Coordinates should read **N48-30.3 E007 34.3** (N48-30-19.40 E007-34-19.10)

Frequency **115.6 MHz**

Navdata will be updated effective AIRAC cycle 2302.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Friday, 20th January 2023

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>

For any inquiries, please contact fms.support@lhsystems.com