



AN AIRBUS COMPANY

ERROR NOTIFICATION BULLETIN

NAVBLUE Reference: 2211-02E

Notification Published date: 03-11-2022

Product Affected: Navigation+

AIRAC Cycle: 2211

Effective Date: 03-11-2022

Country: Australia

Subject: Waypoints NIROK and PROBO (YB) Incorrectly renamed

Source: NOTAM K0974/22

Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2211

Waypoints NIROK and PROBO (YB) were incorrectly renamed for cycle 2211 instead of cycle 2212.

NIROK 254440.1S 1512929.5E renamed to BESBO

PROBO 220032.0S 1495704.3E renamed to EMSUP

These changes will be incorporated in NAVBLUE databases for cycle 2212