



AN AIRBUS COMPANY

## ERROR NOTIFICATION BULLETIN

**NAVBLUE Reference:** 2211-05E

**Notification Published date:** 22-11-2022

**Product Affected:** Navigation+

**AIRAC Cycle:** 2211

**Effective Date:** 03-11-2022

**Country:** Brazil

**Subject:** LEITE LOPES (SBRP)

**Source:** Brazil MAP 221103

**Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2211**

**LEITE LOPES (SBRP)**

**CAUTION:** Procedure RNAV RWY 18 missed approach hold at RP007 has been coded with an incorrect right turn in NAVBLUE databases. The correct turn should be a left turn.

**These changes will be incorporated in NAVBLUE databases for cycle 2213**