



AN AIRBUS COMPANY

## OMITTED NOTIFICATION BULLETIN

**NAVBLUE Reference:** 2212-01O

**Notification Published date:** 23-11-2022

**Product Affected:** Navigation+

Please note that the following information has not been incorporated into NAVBLUE databases for cycle 2212

The below information is under state query and has been omitted from NAVBLUE databases until the query has been resolved.

**Source:** Iran (OIIB) AIRAC AIP Amd 03/20

### NOT IN NAVBLUE DATABASES:

Due to a pending state query the aerodrome and airspace information for OIIB has not been added to the database.

is awaiting state information clarification.

**Source:** Democratic Republic of Congo (FZNP) AIP amendment 4-20

### NOT IN NAVBLUE DATABASES:

The change of THR coordinates on RWY 11/29 at FZNP has not been included in Navblue databases due to an outstanding state query.

is awaiting state information clarification.

**Source:** Mauritania (GQNS) ASECNA AIP amendment 11-20

### NOT IN NAVBLUE DATABASES:

The RWY length of 1600m for RWY 06/24 at GQNS has not been included in Navblue databases due to an outstanding state query.

is awaiting state information clarification.

**Source:** Kenya AIP Supplement 72 to 73-21

### NOT IN NAVBLUE DATABASES:

Runway 26 displaced threshold coordinates not there, state query has been raise and waiting for their response



AN AIRBUS COMPANY

## OMITTED NOTIFICATION BULLETIN

is awaiting state information clarification.

**Source:** Papua New Guinea (AYTB) Flight Supplement 210715 and NOTAM A0054/22

### NOT IN NAVBLUE DATABASES:

Approach procedure NDB/DME (via OKT) CLOUDBREAK – Due to the relocation of Navaid by NOTAM and state has not revised this approach procedure based on the new location of OKT NDB/DME.

is awaiting state information clarification.

**Source:** Costa Rica AIRAC Amd 28-22

### NOT IN NAVBLUE DATABASES:

All changes to the airway UZ512 and UM328 in Navblue databases due to an outstanding state query.

is awaiting state information clarification.

**Source:** Sudan AIRAC AIP Amd 01-22

### NOT IN NAVBLUE DATABASES:

All changes to the airway UN311 and UP556 due to an outstanding state query.  
- Changes to airway UP556 due to incorrect order of fix on the airway segment due to an outstanding state query.  
- Changes to the direction of the segment KAFIA-ALMAM on airway A410 due to an outstanding state query.

is awaiting state information clarification.

**Source:** Russia (UHMP) AIP 220519

### NOT IN NAVBLUE DATABASES:

RWY 35 Approaches: GLS RWY 35, ILS X RWY 35, ILS Y RWY 35, ILS Z RWY 35, LOC X RWY 35, NDB X RWY 35, NDB Y RWY 35, NDB Z RWY 35, RNAV RWY 35 and VOR RWY 35 procedures are suspended from the database because of THR displacement and Vertical Angle discrepancies (Notam C2088/22).

is awaiting state information clarification.

**Source:** Australia (YPDN) AIRAC AIP Supplement H42/22



AN AIRBUS COMPANY

## OMITTED NOTIFICATION BULLETIN

### NOT IN NAVBLUE DATABASES:

YPDN Approaches RNP X RWY 11, RNP X RWY 29, RNP Y RWY 11 and RNP Y RWY 29 have been omitted due to the arc centre fix coordinates not being published.

is awaiting state information clarification.

**Source:** Bolivia (SLCB) NOTAM A0767/22

### NOT IN NAVBLUE DATABASES:

SIDs TEREP 3, TEDOK 3, ATAVO 2, MEXAM 2 VAREB 3 have been omitted due to NDB R (COCHABAMBA Freq 402) being withdrawn.

is awaiting state information clarification.

**Source:** Bolivia AIP Amd 37-19

### NOT IN NAVBLUE DATABASES:

SLBJ RWY 01/19 updates from AIP Amd 37-19 not incorporated as awaiting state response concerning RWY length.

is awaiting state information clarification.

**Source:** Indonesia (WIDD/WIDN) AIP 220811

### NOT IN NAVBLUE DATABASES:

Due to the decommissioning of NDBs JAYBEE [JB] & KONGKONG [KK] and absence of any chart updates from Indonesia, the following procedures are suspended:

WIDD SID WEST POINT Two Charlie  
WIDD SID WEST POINT Two Delta  
WIDD STAR WEST POINT Two Charlie  
WIDD STAR WEST POINT Two Delta  
WIDN SID WEST POINT One Alfa  
WIDN SID WEST POINT One Bravo  
WIDN STAR WEST POINT One Alfa  
WIDN STAR WEST POINT One Bravo

is awaiting state information clarification.

**Source:** Malaysia (WMKP) AIRAC Amd 04/22

### NOT IN NAVBLUE DATABASES:



AN AIRBUS COMPANY

## OMITTED NOTIFICATION BULLETIN

KAMBU transition for approach RNP Z RWY 04 has been omitted from NAVBLUE databases due to the state not publishing the coordinates of waypoint KP504.

is awaiting state information clarification.

**Source:** Brazil (SSUM) MAP AIRAC Amd 2212A1

### NOT IN NAVBLUE DATABASES:

Approaches RNP Z RWY 04, RNP Z RWY 22 and SID OMNI RWY 04/22 have not been included in NAVBLUE databases because the state has not provided sufficient information regarding the runways.

is awaiting state information clarification.

**Source:** Botswana AIP Amd 01/22

### NOT IN NAVBLUE DATABASES:

Please note that airport FRANCISTOWN/ P G MATANTE has been published with ICAO Code FBPM due to an ongoing query with the state. The ICAO code has also been mentioned in documentation as FBPT, we wait for confirmation from the state.

is awaiting state information clarification.